



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
April 18, 2008

Supervisor R

Mine Name: Windy 3	Permit Number: S/053/0071
Operator Name: Color Country Rock, LLC	Inspection Date: April 9, 2008
Inspector(s): Lynn Kunzler	Time: 10:00 am
Other Participants: Russell Shriener, BLM	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

This is a relatively small operation (about 2 acres of disturbance). Although the site is considered active, there has been no apparent activity this year. There was a small area adjacent to the disturbed area that was marked off to protect a cultural site. The site was clean, and no erosion problems noted (light rain during inspection). The site appears to be in compliance.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The Division does not have record of a reclamation surety for this site. A follow-up with the BLM and/or operator is needed to determine if BLM has a surety or other reclamation agreement, and to have the Division named on the surety. A reclamation contract may also be required. Continue to monitor the site when in the area.

Inspector's Signature LK

LK:pb

cc: Preston Hafen, Operator
Russell Shriener, BLM

O:\M053-Washington\S0530071-Windy\Inspections\Insp-04092008.doc